



NOTES:

1. A SIDEWALK TRIP HAZARD EXISTS IF THERE IS A VERTICAL HEIGHT DIFFERENCE BETWEEN ADJACENT SIDEWALK PANEL SECTIONS.
2. IF THE SIDEWALK IS RAISED NOT MORE THAN ONE (1) INCH AND THE CONCRETE EDGES ARE SOLID, THE CONCRETE MAY BE GROUND TO REMOVE THE TRIP HAZARD.
3. FOR A TRIP HAZARD OF $\frac{1}{2}$ ", GRIND BACK A MINIMUM OF SIX (6) INCHES.
4. FOR A TRIP HAZARD OF BETWEEN $\frac{1}{2}$ " AND 1", GRIND BACK A MINIMUM OF TWELVE (12) INCHES.
5. FOR A TRIP HAZARD OF MORE THAN 1", REMOVE AND REPLACE ENTIRE PANEL.

	STANDARD DRAWING TITLE		DRAWING NUMBER
	SIDEWALK TRIP HAZARD DETAIL		
		SCALE	DATE
		N.T.S.	